

**TENNESSEE DEPARTMENT OF ENVIRONMENT AND CONSERVATION**

Division of Water Resources

William R. Snodgrass Tennessee Tower, 312 Rosa L. Parks Avenue, 11th Floor, Nashville TN 37243

1-888-891-8332 (TDEC)

Compliance Inspection for General NPDES Permit for Stormwater Discharges from Construction Activities (CGP)

Site/Project Name:	Moore County Solar CGP	NPDES Tracking Number:	TNR183282
Street Address or Location:	8753 Lynchburg Highway3279 Cumberland Springs Rd	Date Coverage was Issued:	24-JUN-25
Site Description:	Clearing, grading, installation of infrastructure for development of a solar photovoltaic power station	Start Date:	23-JUN-25
County(ies): Moore	EFO: Columbia	MS4 Jurisdiction:	
		Estimated End Date:	31-MAY-27
		Latitude (dd.dddd):	35.359503
		Longitude (-dd.dddd):	-86.277305
		Acres Disturbed:	1548
		Total Acres:	

Name of Permittee (Developer/Operator):	LPL Solar, LLC		
Name of Official Contact: Michael Cottle	Email: mcottle@lplsolar.com	Contact Phone: 954-205-6670	
Address: 3116 S Andrews Ave	City: Ft. Lauderdale	State: FL	Zip: 33316

Construction Phase:	☐ Site preparation	☐ Grading	☒ Construction	☐ Final Stabilization
Inspection Purpose:	☐ Routine	☐ Follow-up	☒ Complaint	☐ NOT

	Yes	No	Comments
Have all construction activities stopped and 70% uniform permanent cover established?	☐	☒	
Notable impacts to waters as a result of site activities/discharges?	☒	☐	See note 1
Evidence of insufficiently treated stormwater discharges at outfall locations?	☒	☐	See note 2
Evidence of structural EPSC measure failure/absence?	☒	☐	See note 3
Evidence of non-structural EPSC measure failure/absence?	☐	☒	
Unauthorized discharges?	☒	☐	See note 1
Evidence of offsite impacts?	☐	☒	Not observed during inspection.
Evidence of construction buffer disturbance?	☐	☒	
Compliance Evaluation: Any Y = recommend NOV/EAR or follow-up - date: ____ Any Y = recommend follow-up (email, letter, inspection, etc.) - date: ____			

	Yes	No	Comments
Are copies of the SWPPP & inspection reports on site or made available?	☒	☐	
Has SWPPP been implemented & satisfactory?	☐	☒	See note 2
Are 2/week inspections being performed?	☒	☐	
Are inspection reports completed & signed?	☒	☐	
Are inspection reports filled out by a qualified EPSC inspector?	☒	☐	
Compliance Evaluation: Any N = recommend follow-up (email, letter, inspection, etc.) date: ____			

	Yes	No	Comments
Are there ARAP violations or unauthorized stream/wetland alteration?	☐	☒	
Compliance Evaluation: Y = perform follow-up ARAP inspection - date: ____			


Notes:

- 1) Evidence of sediment within receiving streams was not observed on day of inspection, but based on previous pictures and information provided during inspection it is likely sediment made it to downstream waters.
- 2.) For outfall sampling purposes below basins, please ensure all areas downgradient of basin outfall structures are stabilized. This will ensure the outfall pipe samples are an accurate representation of stormwater discharges leaving each drainage area.

- 3) As mentioned in note 2, conduct stabilization measures below basin outfalls, including rip rap and/or vegetation as needed. Silt fence repairs in several zones are needed, EPSC clean outs for >50% capacity, stabilization needed in several areas, see points below.
- 4) Any areas on site that are inactive for >14 days require stabilization.
- 5) Please provide inspection records for the past 2 months for basins 1, 2, and 16 for further evaluation of sediment discharges that occurred. Additionally, provide rain gauge date for basins 1, 2, and 16.
- 6) A total of 28 out of the 35 basins were inspected during the site visit. Inspection inventory of basin deficiencies and recommendations:

- Zone 1) Basin 1 – Sediment loss, unauthorized discharge. Water being pumped from Basin 2 to reduce pond levels to help with pipe repairs may be contributing to turbid discharges from Basin 1. Recommend lowering pump rate from Basin 2 to Basin 1 if possible.
- Basin 2 – Sediment loss, unauthorized discharge. Pipe in Basin 2 froze and was damaged during previous cold weather event which may have contributed to sediment loss. Clean-up required past silt fence below basin discharge.
- Zone 10) Basin 13 – Basin cleanout.
Basin 21 – Silt fence cleanout.
Basin 19 – Silt fence cleanout, stabilize adjacent area next to bore line.
- Zone 11a) Basin 8 – Silt fence repair.
Basin 22 – Silt fence repair.
- Zone 11b) Basin 24 – Silt fence cleanout.
Basin 26 – Silt fence repair.
Basin 28 – Silt fence cleanout.
Basin 30 – Silt fence repair.
Basin 31 – Silt fence repair.
- Zone 12) Basin 16 – Sediment loss, unauthorized discharge. Cleanup activities had already taken place prior to visit.
- Zone 15) Basin 35 – Silt fence repair.
- Multiple Zones and Basins: stabilization measures including vegetation and/or riprap required below basin discharge pipe.
- 7) Please provide our office with a status update of site conditions once all repairs and maintenance have occurred onsite.

-Site photos are representative and not a complete inventory of the entire site

On-Site Contact (if available)			
On-Site Contact Name (Print):	On-Site Contact Title:	Signature:	Date:
TDEC Personnel/Information			EFO: Columbia EFO 1421 Hampshire Pike Columbia, TN 38401
	Signature:	Date: 2/13/26	
Inspector's Name (Print): Alex Fleming		Time: 0930	



Zone 15 – Basin 34 Stabilize below outfall 2026-02-13 11:33:27-06:00



Zone 15 – Basin 35 Stabilize and Repair SF 2026-02-13 11:38:53-06:00



Zone 15 – Basin 34 Stabilize 2026-02-13 11:33:54-06:00



Zone 15 Basin 35 SF 50% 2026-02-13 11:40:19-06:00



DIRECTION
121 deg(T)

35.35761°N
086.30593°W

ACCURACY 5 m
DATUM WGS84



Zone 1 Basin 2

Sediment Loss over SF

2026-02-13
10:37:37-06:00

DIRECTION
123 deg(T)

35.35906°N
086.30548°W

ACCURACY 6 m
DATUM WGS84



Zone 1 Basin 1

Sediment Loss

2026-02-13
10:42:21-06:00

DIRECTION
250 deg(T)

35.34764°N
086.29331°W

ACCURACY 4 m
DATUM WGS84



Zone 10 Basin 19

Clean out SF

2026-02-13
12:59:36-06:00

DIRECTION
297 deg(T)

35.34827°N
086.29356°W

ACCURACY 4 m
DATUM WGS84



Zone 10 - Basin 19

Stabilize area
adjacent to bore line

2026-02-13
13:01:02-06:00

DIRECTION
191 deg(T)

35.34821°N
086.29131°W

ACCURACY 4 m
DATUM WGS84



Zone 10 Basin 21

Clean out SF

2026-02-13
12:49:31-06:00

DIRECTION
188 deg(T)

35.34529°N
086.28788°W

ACCURACY 14 m
DATUM WGS84



Zone 10 Basin 13

Stabilize

2026-02-13
13:16:39-06:00

DIRECTION
266 deg(T)

35.34277°N
086.28628°W

ACCURACY 4 m
DATUM WGS84



Zone 12 Basin 16 Sump
9

Clean out SF

2026-02-13
11:58:57-06:00

DIRECTION
254 deg(T)

35.33976°N
086.27456°W

ACCURACY 4 m
DATUM WGS84



Zone 13 Basin 17

Stabilize

2026-02-13
12:30:10-06:00